

EtherCAT : Errata for Industrial SDK 1.1.1/2.1.1 and PRU-ICSS-EtherCAT 01.00.00

Single datagram accessing multiple FMMU mapped areas using LRD/LWR commands

- **Issue/Failure Description or state**

- SDOCM00092510/PINDSW-47 : Single datagram accessing multiple FMMU mapped areas in a single slave will only update the data corresponding to first FMMU in datagram

- **Conditions in which failures occur**

- Single datagram accessing multiple FMMU mapped areas in single slave.

FMMU0(0x1000:0x1007)->SM2 (Write SM)

FMMU1(0x1000:0x1007)->SM3 (Read SM)

FMMU2(0x1008:0x100F)->SM4 (Write SM)

FMMU3(0x1008:0x100F)->SM5 (Read SM)

- Single LRD to access (0x1000:100F) will only access SM3
- Single LWR to access (0x1000:100F) will only access SM2
- 2 LRD/LWRs are required in this case to access both pair of SMs - LRD1/LWR1(0x1000:0x1007) and LRD2/LWR2(0x1008:0x100F)

- **Root cause**

- Increased code memory requirements in firmware to implement this support

- **Work around**

- For above example instead of one LRD datagram to logical address 0x1000 and length 16, master needs to send two LRD datagrams, one to logical address 0x1000 and length 8 second to logical address 0x1008 and length 8 or use LRW in place of LRD/LWR which is more efficient for most of the use cases

NOTE: This issue will not be fixed

PD/PDI watchdog counter issue

- **Issue/ Failure Description or state**

- SDOCM00098105/PINDSW-72: PDI/PD watchdog counter incremented by 1 whenever PDI/PD watchdog is disabled using EtherCAT master

- **Conditions in which failures occur**

- Whenever EtherCAT master disables WD by writing zero to respective Watchdog Time registers (0x410:0x411 or 0x420:0x421)

- **Root cause**

- This is PRU-ICSS h/w behavior

NOTE: This issue will not be fixed

LRD access on unused registers

- **Issue/ Failure Description or state**

- SDOCM00098950/PINDSW-74: LRD access on unused registers results in WKC increment

- **Conditions in which failures occur**

- LRD access on unused registers result in WKC increment

- **Root cause**

- Firmware does not support register protection in LRD mode at this moment, it requires more firmware footprint to support, this minor spec compliance does not justify the footprint increase and no Write Only registers in ESC

NOTE: This issue will not be fixed

LRW access to non-interleaved input and output process data of multiple slaves does not work

- **Issue/ Failure Description or state**

- SDOCM00105048/PINDSW-141: LRW access to non-interleaved input and output process data of multiple slaves does not work. SOEM accesses slaves in LRW mode this way

- **Conditions in which failures occur**

- Single LRW datagram accessing FMMU mapped areas in multiple slaves and PD out is mapped
FMMU0(0x1000:0x1007)->SM2 #1(Write SM) FMMU1(0x1008:0x100F)->SM2#2 (Write SM)
FMMU2(0x1010:0x1017)->SM3 #1 (Read SM) FMMU3(0x1018:0x101F)->SM3#2(Read SM)
 - Single LRW access from (0x1000:101F)

- **Root cause**

- Increased code memory requirements in firmware to implement this support as well as non-interleaved access I/O data is not a very optimal use of EtherCAT – it increases the cycle time overhead/datagram size and not effective use of LRW datagram which can perform read and write in the same cycle.

- **Work around**

- Use LRD/LWR datagram to access process data
- Use LRW datagram to access process data
 - Input and output overlaid on the same logical address range (TwinCAT usage)
 - Input and output of a given slave back to back in logical address space
 - FMMU0(0x1000:0x1007)->SM2 #1(Write SM) FMMU1(0x1008:0x100F)->SM3#1 (Read SM)
 - FMMU2(0x1010:0x1017)->SM2 #2 (Write SM) FMMU3(0x1018:0x101F)->SM3#2 (Read SM)

Issues fixed in PRU-ICSS-EtherCAT 01.00.00 (Firmware build 0x3e3)

**NOTE: PRU-ICSS-EtherCAT 01.00.00 firmware is
compatible with Industrial SDK 2.1.1.2 and
Industrial SDK 1.1.1.1 EtherCAT firmware**

The register 0x0980 (mandatory writable register) is read-only

- **Issue/ Failure Description or state**

- SDOCM00121527/SDOCM00121996/PINDSW-512 - The register 0x0980 (mandatory writable register) is read-only

- **Conditions in which failures occur**

- EtherCAT Master performs a write (APWR, FPWR, BWR) to ESC offset 0x980

- **Root cause**

- Register permission was set read only for 0x980 from driver side

- **Workaround**

- In `bsp_esc_reg_perm_init`, add following line if not already
 - `pRegPerm->reg_properties[0x980] = TIESC_PERM_RW;`

Executing CTT on OUT port has malformed ECAT packets

- **Issue/ Failure Description or state**

- SDOCM00121537/PINDSW-514: Executing CTT on OUT port has malformed ECAT packets

- **Conditions in which failures occur**

- Conformance Tests executed from OUT port (Port1) of ESC and observe the traffic using a packet sniffer

- **Root cause**

- This unusual configuration exposed cycle budget issues in the firmware causing TX to underrun, additional cycle budget required when doing process data read using APRD command

- **Workaround**

- NA

Circulating frame handling immediately post power reset

- **Issue/ Failure Description or state**

- SDOCM00121961/PINDSW-556 - Circulating frame handling immediately post power reset for AM437x and AM57x IDK

- **Conditions in which failures occur**

- Reboot the slave and send frames with circulating bit set.

- **Root cause**

- Fixed init value of DL status Port1 to OPEN (01) than default CLOSE (00), in order to respond to the packets from Host PC towards Port1

Packet loss during state change from INIT to PREOP in redundancy

- **Issue/ Failure Description or state**

- SDOCM00122000/PINDSW-560 - Packet loss during state change from INIT to PREOP in redundancy mode

- **Conditions in which failures occur**

- Four slaves connected forming a redundant network in DC mode and TwinCAT3 master is used
- A state change from INIT to PREOP has a lost frame.

- **Root cause**

- DL control register write from master causing change in ESC Port configuration. Since DL Loop Control state m/c did not wait for ongoing frame activity @ reverse path to complete during port closure, resulting in a broken frame [depending on number of slaves and frame size]

Issues fixed in 1.1.1 (Firmware build 0x3d7)

NOTE: Industrial SDK 1.1.1.1 firmware is compatible with 2.1.1.2 EtherCAT firmware for AM335x (firmware/v1.0 sub folder). AM437x can also use the same firmware provided max 8KB process data memory is required for use cases

PDO corruption issue post SDO/CoE access

- **Issue/ Failure Description or state**

- PINDSW-681 : PDO corruption issue post SDO/CoE access

- **Conditions in which failures occur**

- Master sends PDO and SDO one after the other. If first byte (is a status and not changed in normal circumstances) of PDO is changed at SDO in the vicinity, it is judged as error

- **Root cause**

- This is a side effect of DC bug fix added in firmware build 0x3c0. This may cause register corruption under very rare circumstances. Depending on the value of firmware state variables above code can corrupt pointers used by PDO path. This DC bug fix was corrected in firmware build 0x3d3 onwards

- **Workaround**

- Recommend customers using Industrial SDK 1.1.0.10/2.1.1.2 to upgrade to firmware build 0x3d7 [Industrial SDK 1.1.1.1]or 0x3e3 [PRU-ICSS-EtherCAT 01.00.00]

Frame with long preamble and SFD but valid FCS is dropped by ESC

- **Issue/ Failure Description or state**

- SDOCM00120927/PINDSW-452: Frame with long preamble and SFD but valid FCS is dropped by ESC

- **Conditions in which failures occur**

- EtherCAT frame with long preamble (> 7 bytes or 14 nibbles) is send to TI ESC

- **Root cause**

- PRU-ICSS MII h/w default settings, treats long preamble as error and generates 5a 5a 5a 5a odd nibble response even when EtherCAT frame is valid with correct FCS

- **Workaround**

- Disable long preamble error detection in PRU-ICSS MII h/w by setting 1 to below registers instead of 0xE1 (HW reset value)

MII_RT RXPCNT0 (For Port0)	0x4a33_2048
MII_RT RXPCNT1 (For Port1)	0x4a33_204C

Slaves do not go to OP state in DC mode when TI ESC is reference slave in DC Slave Mode

- **Issue/ Failure Description or state**

- SDOCM00121174/PINDSW-477: Slaves do not go to OP state in DC mode when TI ESC is reference slave in DC slave mode (IgH or Acontis EtherCAT master)

- **Conditions in which failures occur**

- DC Slave mode is configured at master (IgH or Acontis EtherCAT master) and TI ESC is reference slave

- **Root cause**

- Firmware used System Time Delay (non-zero) to enable drift compensation loop at slave

- **Workaround**

- Set non-zero System Time Delay(0x928:0x92b) value for reference slave – say 1ns

Error counter discrepancy with ET1100

- **Issue/ Failure Description or state**
 - SDOCM00121177/PINDSW-479: Error counter discrepancy with ET1100
- **Conditions in which failures occur**
 - Rx Invalid Frame Counter Port0/1 (0x300/0x302) counts EtherCAT parse errors and short frames with valid FCS
 - ECAT processing counter (0x30c) does not count following
 - Physical Layer Errors
 - Non-EtherCAT frames if 0x100.Bit0 == 1
 - Circulating bit=1 and Port0 is Automatically Closed
 - Detection of forwarded error was not possible when SFD was missing in frame due to h/w truncating frame beyond max preamble count marker (16 nibbles including SFD - SDOCM00120927)
- **Root cause**
 - Spec interpretation issue due to ambiguity in relevant sections
- **Workaround**
 - None

Issues fixed in 2.1.1 and 1.1.0.10 (Firmware build 0x3cb)

DC sync is not working correctly when System Time PDI controlled Time synchronization is enabled

- **Issue/ Failure Description or state**

- SDOCM00119732/PINDSW-348: DC sync is not working correctly when System Time PDI controlled Time synchronization is enabled

- **Conditions in which failures occur**

- When System Time PDI control is enabled (SYSTEM_TIME_PDI_CONTROLLED is set to 1 in tiescbsp.h) and Host CPU is initiating DC drift compensation control loop

- **Root cause**

- Firmware was updating DC shadow registers when System Time PDI control is enabled, this caused inconsistent behavior when System Time PDI controlled mode was active

- **Workaround**

- None

LATCH0/1 misses to latch positive edge sometimes in continuous mode

- **Issue/ Failure Description or state**

- SDOCM00119422/PINDSW-332: LATCH0/1 misses to latch positive edge sometimes in continuous mode

- **Conditions in which failures occur**

- Latch0 is continuous mode

- **Root cause**

- Firmware used Latch0 pin raw status to allow saving H/W latch value to register. Depending on the latch input pulse duty cycle probability of positive edge latching reduced significantly

- **Workaround**

- Potential workaround is to increase input pulse width (duty cycle 50-50)

Inconsistency of 64-bit DC System Time

- **Issue/ Failure Description or state**

- SDOCM00119421/PINDSW-331: Inconsistency of 64-bit DC System Time

- **Conditions in which failures occur**

- When EtherCAT master reads DC system Time (0x910:0x917), back to back inconsistency seen w.r.t to MSW (System Time High)

- **Root cause**

- PRU-ICSS IEP counter is 32-bit HW counter, System Time High is managed by firmware and there were race conditions in firmware around 32-bit time overflow (~ every 4.2s) handling

- **Workaround**

- Use 32-bit DC System Time (0x910:0x913)

Port0 in Auto Close mode does not always open Port on a valid frame arrival post link up event

- **Issue/ Failure Description or state**

- SDOCM00118530/PINDSW-299: Port0 in Auto Close mode does not always open Port on a valid frame arrival post link up event

- **Conditions in which failures occur**

- Modify the contents of register DL Control(0x0100) from F401 to F501. Disconnect and reconnect cable (multiple times) from master to slave quickly. The slaves do not come to OP state.

- **Root cause**

- Fixed a bug with DL link loop control state m/c, firmware opened the port on valid frame in AutoClose mode only when link change event occurred along with this

- **Workaround**

- Configure Port0 in Auto Mode always

WKC update issues with unsupported port error counter access

- **Issue/ Failure Description or state**

- SDOCM00118196/PINDSW-286: WKC update issues with unsupported port error counter access

- **Conditions in which failures occur**

- EtherCAT master accessing port error counters for non-existent port incrementing WKC

- **Root cause**

- Due to a misconfiguration of register configuration from driver to firmware, those registers were treated read only by firmware

- **Workaround**

- Apply patch mentioned in <https://cqweb.ext.ti.com/cqweb/main?command=GenerateMainFrame&service=CQ&schema=SDO-Web&contextid=SDOWP&entityID=SDOCM00118196&entityDefName=IncidentReport&username=readonly&password=readonly>

Write to MI PDI Access State register (0x517) clears ESC Type (0x0000) register

- **Issue/ Failure Description or state**

- SDOCM00118195/PINDSW-285 : Write (0, 0xFE, 0xFF) to MII Management PDI Access State register (0x517) clears ESC Type (0x0000) register

- **Conditions in which failures occur**

- Write (0, 0xFE, 0xFF) to MII Management PDI Access State register (0x517) clears ESC Type (0x0000) register

- **Root cause**

- TI ESC does not support switching PDI and ECAT access via ECAT interface, so this access shall be forbidden. There was a bug in the firmware which caused null pointer write during such access

Dummy traffic on link loss in a passive network when link partner is non-TLK PHY

- **Issue/ Failure Description or state**

- SDOCM00118194/PINDSW-284: Dummy traffic on link loss in a passive network when Link partner is non-TLK PHY

- **Conditions in which failures occur**

- In a network of slaves (even with no master connected) when Port0 link is broken, randomly activity LED of Port1 blinks. This happens when TI ESC connected to non-TLK link partner

- **Root cause**

- Issue is a side effect of enabling Fast RXDV detection in TLK, this causes a burst of RX_ERRs to be generated during link loss as PHY detects a false RX_DV on seeing J symbol – and leads to link activity on cable break (this is normal and allowed though). This also causes periodic false RX_DV depending on link partner in a network not connected to any EtherCAT master

- **Workaround**

- Disable Fast RX_DV detection by clearing Bit1 of SWSCR1 (0x9)

Clear UDP checksum on processing of UDP encapsulated EtherCAT packets

- **Issue/ Failure Description or state**

- SDOCM00118024/PINDSW-275: Clear UDP checksum on processing of UDP encapsulated EtherCAT packets

- **Conditions in which failures occur**

- When UDP encapsulated EtherCAT frames are send from PC tool with non-zero checksum, HLOS like windows, drops UDP packets with non-zero checksum when it validates and this causes an interop issue. Clearing checksum is a requirement of tunneling over UDP...

- **Root cause**

- Firmware did not clear UDP checksum as this was not a mandatory requirement

Issues fixed in 2.1.0.1

**NOTE: 2.1.0.1 EtherCAT firmware for AM335x
(firmware/v1.0 sub folder) is compatible with
Industrial SDK 1.1.0.8**

Rx Time Port1 (0x904) time stamping not done correctly when write to 0x900 is done cyclically

- **Issue/ Failure Description or state**

- SDOCM00108541/PINDSW-174: Rx Time Port1 (0x904) time stamping is missed when write (BWR) to 0x900 is done cyclically

- **Conditions in which failures occur**

- When EtherCAT master cyclically writes to 0x900 register and two ports of EtherCAT slave are active
- For first write to 0x900 after a link up event randomly

- **Root cause**

- Parsing algorithm was not scheduled on time due to cycle budget crunch in firmware and this resulted in RX L2 FIFO overflow and parsing errors
- Parsing algorithm and firmware optimizations were done to fix overflow
- Parsing algorithm had a bug : which missed to detect write to 0x900 when datagram address (ado) word is split into two banks of L2 FIFO as separate bytes

ESC error counter clear behavior is not ET1100 compliant

- **Issue/ Failure Description or state**
 - SDOCM00116053/PINDSW-217: Writing a single byte in range 0x0300:0x030b does not clear complete range
- **Conditions in which failures occur**
 - ESC register range 0x300:0x30b is non-zero
 - Write to any register in this range
- **Root cause**
 - Firmware supports write clear per byte for error counters

PDI ISR on h/w pin is not generated for ICEv2

- **Issue/ Failure Description or state**

- SDOCM00117382/PINDSW-250: PDI ISR on h/w pin is not generated for ICEv2 even though PDI ISR DIGIO pin selection register (0xE0A) is not set to 0xFF

- **Conditions in which failures occur**

- If PDI ISR over DIGIO pin is enabled and pinmux for this pin is configured correctly to select pr1_edio_data_outN function

- **Root cause**

- Due to a bug in driver, PRU-ICSS DIGIO SW dataout mode is not enabled. Register Offset PRU_IEP_DIGIO_CTRL_REG was used instead of PRU_IEP_DIGIO_EXP_REG

SM0/1 events may trigger PDI ISR even when they are masked

- **Issue/ Failure Description or state**

- SDOCM00117503/PINDSW-253 : SM0/1 (mailbox) events may trigger PDI ISR even when they are masked

- **Conditions in which failures occur**

- It has been reported that when TwinCAT does CoE access in OP mode, ARM sees more SM2 events than number of actual cyclic data events.

- **Root cause**

- This is root caused to a firmware issue, in the scenarios when ARM clears PDI ISR late (E.g.:- SM2 event) and other AL events are raised (E.g.:- mailbox event) even though masked. Firmware re-triggers PDI ISR when previous SM2 event (or any enabled event at AL event mask register) is pending in AL event IRQ register and any of disabled event (at AL event mask register) occurs meanwhile Fixed firmware to use only newly generated enabled event to trigger interrupt to host

- **Work around**

- Clearing the AL event IRQ events as early as possible

SM2 first byte data corruption is seen randomly

- **Issue/ Failure Description or state**

- SDOCM00117692/PINDSW-259 : SM2 first byte data corruption is seen randomly. This can also lead to ESC type register corruption

- **Conditions in which failures occur**

- When PDI side mailbox read or write occurs and ECAT is reading the same buffer or just switched to corrupted buffer

- **Root cause**

- Firmware used register R11 as pointer to ECAT and AL event request registers. This is corrupted (but unnoticed as broadside access XIN [register file load from scratch register bank] was made when PDI side mailbox read or write occurs) and post PDI operation, firmware updates AL/ECAT event request register. XIN loads SM start address pointers to

register file and this explains random corruption of first few bytes of SM2

Issues fixed in 1.1.0.8

SYNC0 jitter increases with distance of slave from reference

- **Issue/ Failure Description or state**

- SDOCM00097012/PINDSW-62 : SYNC0 jitter increases with distance of slave from reference

- **Conditions in which failures occur**

- TI ESC in a large network of slaves - shows variable jitter which increases with distance of the slave from reference slave

- **Root cause**

- Drift compensation algorithm improvements are made, speed counter filter depth increased

Frame corrupted when LRW issued with logical address ending just before FMMU logical start address

- **Issue/ Failure Description or state**

- SDOCM00115000/PINDSW-213: Frame corrupted when LRW issued with logical address ending just before FMMU logical address

- **Conditions in which failures occur**

- FMMU start address is X
- LRW datagram last byte accessed at X-1

- **Root cause**

- Fixed the firmware bug with logical address boundary check

Process data corruption when PDI update is slow (slave running non-real time OS)

- **Issue/ Failure Description or state**

- SDOCM00115132/PINDSW-214: Process data corruption when PDI update is slow (slave running non-real time OS)

- **Conditions in which failures occur**

- Large process data (say 256 bytes) exchanged between slave and master
- PDI process data write is delayed more than one cycle time
- PLC sees corrupted Process Data Input

- **Root cause**

- Fixed a bug in the firmware with triple buffer pointer handling

CTT TF1100.2.5 Mailbox Read Service Repeat 2 regression failure

- **Issue/ Failure Description or state**

- SDOCM00115487/PINDSW-215 : CTT TF1100.2.5 Mailbox Read Service Repeat 2 regression failure

- **Conditions in which failures occur**

- When above CTT test is repeated in regression mode (≥ 10000 times) sporadic failure is seen

- **Root cause**

- There was an offset change for `t_host_interface.sm_config_ongoing` variable in firmware due to merge issue which was not migrated to host interface, so stack/application missed the SM busy status

- **Work around**

- Update `t_host_interface` struct in `tiescbsp.h` as shown below

```
typedef struct {  
    Uint8 reserved1[0x90];  
    Uint32 system_time_low;  
    Uint32 system_time_high;  
-   Uint8 sm_config_ongoing;  
-   Uint8 reserved2[7];  
+   Uint16 reserved;  
+   Uint8 sm_config_ongoing;  
+   Uint8 reserved2[5];
```

NOTE: Work around is not needed $\geq 1.1.0.8$

Power on Reset DC filter setting (System Time Filter depth of 4) causes PRU firmware lockup when DC is enabled

- **Issue/ Failure Description or state**

- SDOCM00116155/PINDSW-218: Power on Reset DC filter setting (System Time Filter depth of 4) causes PRU firmware lockup when DC is enabled

- **Conditions in which failures occur**

- Reported by IgH master which did not configure System Time Filter depth and enabled DC mode of operation
- Results in random PRU lock up making device unresponsive to state change and error reset requests from master

- **Root cause**

- Fixed the firmware to avoid this lock up scenario for all supported filter depth
- Recommended filter depths are Speed Counter Filter Depth (12) and System Time Filter Depth (0)

PortX in Auto-close mode opens port incorrectly on Link up event

- **Issue/ Failure Description or state**

- SDOCM00116714/PINDSW-222: PortX in Auto-close mode opens port incorrectly on Link up event

- **Conditions in which failures occur**

- PortX in AutoClose mode, Port can be opened only if a valid frame received over PortX or Write to DL Control (0x100) with “01” via Other port and not on Link Up event
- PortX in AutoClose mode opens on Link Up event

- **Root cause**

- Firmware state m/c bug is fixed

Issues Fixed in 1.1.0.6

In low cycle times with high-jitter masters, ECAT API `bsp_get_process_data_address` fails sporadically

- **Issue/ Failure Description or state**

- SDOCM00113900/PINDSW-200: In low cycle times with high-jitter masters, ECAT API `bsp_get_process_data_address` in file `tiescbsp.c` fails sporadically

- **Conditions in which failures occur**

- When running TwinCAT master on laptop or PC with onboard NIC, this is observed that `bsp_get_process_data_address` returns 0

- **Root cause**

- Fixed a bug with updating `lock_state` (incorrectly) - only address meant to be updated by firmware

When PDI-side register permissions are enabled, Link/Activity LED indications are reversed

- **Issue/ Failure Description or state**

- SDOCM00114419/PINDSW-209: When PDI-side register permissions are enabled, Link/Activity LED indications are reversed

- **Conditions in which failures occur**

- ENABLE_PDI_REG_PERMISSIONS is enabled in tiescbsp.h while building the ethercat application and observe Link and activity LED behavior are reversed while running the app in ICE EVM

- **Root cause**

- The address of PRU MII RX LINK polarity was changed to 0x0E0C in ISDK 1.1.0.5. PDI register permission array did not reflect this, this causes LED task controlling the activity to behave incorrectly